

PNOISE (red) vs NOISE (yellow). 53.6uV/rt(Hz) compared to 100nV/rt(Hz) at 1KHz.

## PSS Setup:


Periodic Steady State Analysis
Engine   Shooting  Harmonic Balance
Fundamental Tones # Name Expr Value Signal SrcId
Wind CAPI Wild Signer Siere
Large 🔽
Clear/Add Delete Update From Hierarchy
Beat Frequency     Beat Period     R("period_calc")     Auto Calculate
Output harmonics Number of harmonics 7
Accuracy Defaults (errpreset)
✓ conservative 📃 moderate 🛄 liberal
Transient-Aided Options
Run transient? • Yes O No O Decide automatically
Detect Steady State 🖌 Stop Time (tstab)
Save Initial Transient Results (saveinit) 📃 no 🕑 yes
Dynamic Parameter
Oscillator 🗹 Oscillator node+ /out Select
Oscillator node- /agnd Select
Calculate initial conditions (ic) automatically
Enable tuning mode analysis
Sweep
New Initial Value For Each Point (restart)
Loadpull
Enabled 🗹 Options

## PNOISE SETUP:

	Periodic N	loise Analysis	;	
PSS Beat Period (se	c) R("per	iod_calc")		
Multiple pnoise				
Sweeptype	default	(Hz)		
Start-Stop	Start	30	Stop	<pre>'iod_calc")</pre>
Stop At Half Fun Sweep Type	damental Freque	ency	⊻ yes	
Automatic	3			
Add Specific Poin Add Points By File				
	_			
Sidebands				
	default 🥑 fulls	-		
Maximum sideb	e contributions up	28 b to the frequ	iency deterr	nined
by PSS time poi		o to the help	iency decen	
Noise Type sam		Sample Ra		
# Event Trig	g TrigVal	Targ	TargVal	. TD
# Event Trig		Targ	TargVal	. TD
# Event Trig	g TrigVal	Targ	TargVal	. TD
# Event Trig	TrigVal	Targ	TargVal	TD Enabled
# Event Trig	TrigVal	Targ	TargVa] d	Enabled ⊻
# Event Trig	TrigVal	Targ	TargVa] d Delay 🔾 S	Enabled 🕑 ampled Phase
# Event Trig	TrigVal agnd 5.000e-0 Delete • Edge Crossin : PM jitter measu	Targ	TargVal d Delay O Sa e measuren	Enabled 🕑 ampled Phase nent node
# Event Trig	TrigVal agnd 5.000e-0 Delete Edge Crossin Positive Outpu	Targ	TargVa] d Delay 🔾 S	Enabled 🕑 ampled Phase
<pre># Event Trig 1 cross out- 1 cross out- Add Change Timing Event Edge Crossing Trigger voltage  </pre>	<ul> <li>TrigVal</li> <li>agnd 5.000e-0</li> <li>Delete</li> <li>Edge Crossin</li> <li>PM jitter measu</li> <li>Positive Output</li> <li>Negative Output</li> </ul>	Targ	TargVal d Delay O Sa e measuren /out /agnd	Enabled ampled Phase hent node Select Select
# Event Trig 1 cross out- 1 cross out- Add Change Timing Event Edge Crossing Trigger	TrigVal agnd 5.000e-0 Delete Edge Crossin Positive Outpu	Targ	TargVal d Delay 🔾 S. e measuren /out	Enabled 🕑 ampled Phase nent node Select
<pre># Event Trig 1 cross out- 1 cross out- Add Change Timing Event Edge Crossing Trigger voltage  </pre>	<ul> <li>TrigVal</li> <li>agnd 5.000e-0</li> <li>Delete</li> <li>Edge Crossin</li> <li>PM jitter measu</li> <li>Positive Output</li> <li>Negative Output</li> </ul>	Targ	TargVal d Delay O Sa e measuren /out /agnd	Enabled ampled Phase hent node Select Select
<pre># Event Trig 1 cross out- 1 cross out- Add Change Timing Event Edge Crossing Trigger voltage  </pre>	<ul> <li>TrigVal</li> <li>agnd 5.000e-0</li> <li>Delete</li> <li>Edge Crossin</li> <li>PM jitter measu</li> <li>Positive Output</li> <li>Negative Output</li> <li>Threshold Vation</li> <li>0.5</li> </ul>	Targ	TargVal d Delay C S e measuren /out /agnd Direction se V	Enabled ampled Phase nent node Select Sleep Time
<pre># Event Trig 1 cross out 1 cross out 4 dd Change Timing Event Edge Crossing Trigger voltage Edge Number</pre>	<ul> <li>TrigVal</li> <li>agnd 5.000e-0</li> <li>Delete</li> <li>Edge Crossin</li> <li>PM jitter measu</li> <li>Positive Outpu</li> <li>Negative Outpu</li> <li>Threshold Va</li> </ul>	Targ	TargVal d Delay O S e measuren /out /agnd Direction	Enabled ampled Phase hent node Select Select

## **PSS Parameters:**

```
Important parameter values in tstab integration:
    start = 0 s
    outputstart = 0 s
    stop = 1.25566 ms
    period = 22.8302 us
    maxperiods = 50
    step = 1.16434 us
    maxstep = 913.207 ns
    ic = all
    useprevic = no
    skipdc = no
    reltol = 1e-06
    abstol(V) = 1 nV
    abstol(I) = 1e-21 A
    temp = -193 C
    tnom = 27 C
    tempeffects = all
    method = gear2only
    lteratio = 3.5
    relref = sigglobal
    cmin = 0 F
    gmin = 1e-24 S
    rabsshort = 1 mOhm
Important parameter values in pss iteration:
    start = 456.611 us
    outputstart = 0 s
    stop = 479.441 us
    period = 22.8302 us
    maxperiods = 50
    steadyratio = 100e-03
    step = 1.16434 us
    maxstep = 57.0754 ns
    ic = all
    useprevic = no
    skipdc = no
    reltol = 1e-06
    abstol(V) = 1 nV
    abstol(I) = 1e-21 A
    temp = -193 C
    tnom = 27 C
    tempeffects = all
    errpreset = conservative
    method = gear2only
    lteratio = 3.5
    relref = alllocal
    cmin = 0 F
    gmin = 1e-24 S
    rabsshort = 1 mOhm
```



The marker on the plot below is where the phoise jitter trigger is set. The waveform is the PSS transient waveform.